

\$1,899

Bronze

\$2,199

Silver

\$2,499

Gold

\$2,799

Platinum

Double Clear Coat

Double Clear Coat

Double Clear Coat

Triple Clear Coat

Triple Clear Coat

Double Clear Coat

Double Clear Coat

Double Clear Coat

Triple Clear Coat

Urethane Base Coat

Urethane Base Coat

Double Urethane Base

Double Urethane Base

Double Urethane Base

Double Urethane Base

- **UV Sunscreen for fading**
- **High Gloss lasts longest**
- **Best color match**
- **OEM Factory Paint**
- **More control, minimal dust**
- **Detail while masking**
- **1 hour base coat tweaking**

- **UV Sunscreen for fading**
- **High Gloss lasts longest**
- **Best color match**
- **OEM Factory Paint**
- **More control, minimal dust**
- **Extra detail while masking**
- **2 hours base coat tweaking**

- **UV Sunscreen for fading**
- **High Gloss lasts longest**
- **Best color match**
- **OEM Factory Paint**
- **More control, minimal dust**
- **Extreme detail while masking**
- **3 hour base coat tweaking**

- **UV Sunscreen for fading**
- **High Gloss lasts longest**
- **Best color match**
- **OEM Factory Paint**
- **More control, minimal dust**
- **Extreme detail while masking**
- **4-6 hours base coat tweaking**
- **Removal of extra items before painting**

*Add \$300 Black, White Paint
 \$350 Color Mix Paint
 \$400 Red, Yellow Paint

*Add \$200 Color Change

*Add \$900 Wet Sand and Buff the New Clear Coat

*Add \$400 Black, White Paint
 \$450 Color Mix Paint
 \$500 Red, Yellow Paint

*Add \$200 Color Change

*Add \$900 Wet Sand and Buff the New Clear Coat

Note: Fading is usually caused by ultraviolet radiation (the sun), But it may also be caused by exposure to greatly contrasting temperatures (hot and cold). This creates a physical stress on the paint, causing microscopic breakdown and accelerating the fading process. Fading is a condition that reduces the overall gloss of the paint to a point where waxing no longer restores a shine.